Printed on : 5/15/2009 12:20:49 AM

							011 1 07 1 07 2 0 0 0 1 2 1 2 0 1 1 0 7 11 1			
National Transportation Safety Board	NTSB ID:	ERA09WA2	23	Aircraft Regist	Aircraft Registration Number: PT-LKH					
FACTUAL REPORT	Occurrenc	e Date: 03/08	3/2009	Most Critical I	Most Critical Injury: Fatal					
AVIATION	(Occurrenc	e Type: Accid	lent	Investigated B	y: Fore	eign			
Location/Time										
Nearest City/Place	State	Zip	Code	Local Time	Time Zone					
Querencia	encia			2030	UTC	UTC				
Airport Proximity: Off Airport/Airstrip	anding Facility:	•	•	•						
Aircraft Information Summary										
Aircraft Manufacturer		Model/Series	S		Type of Aircraft					
BEECH	A36			Airplane						
Revenue Sightseeing Flight: No	Air Medical Transport Flight: No									

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On March 9, 2009, about 2030 coordinated universal time, a Beech A36, Brazilian registration PT-LKH, was destroyed when it impacted terrain near Querencia, Brazil. The pilot was fatally injured. The flight was conducted under Brazilian flight regulations.

According to preliminary information provided by the Brazilian government, the pilot departed on a visual flight from Aragarcas, Brazil, destined for Fazenda Felicidade, Brazil. The pilot encountered weather while enroute, and the airplane impacted terrain some time thereafter.

This investigation is under jurisdiction of the Government of Brazil. For further information contact:

Areonautical Accident Prevention and Investigation Center

SHIS - QI 05 - VI COMAR

Brasila-DF, Brazil

71.615-600

Tel: +55 61 3364 8800 Fax: +55 61 3365 1004 dipaa@cenipa.aer.mil.br

This report is for informational purposes only and only contains information released by, or obtained from, the Government of Brazil.

Updated on Apr 10 2009 12:27PM

National Transportation Safety Board FACTUAL REPORT AVIATION

NTSB ID: ERA09WA223

Occurrence Date: 03/08/2009

AVIATION	nce Type:	 : Ac	cident									
Landing Facility/Approach In	formation											
Airport Name	port ID:	Ai	irport Elevation	vation Runway Used F			Runway Length		Runv	vay Width		
			Ft. MSL	_ N/A								
Runway Surface Type:				_				<u> </u>				
Runway Surface Condition:												
•												
Approach/Arrival Flown: NONE	Ē											
VFR Approach/Landing: None												
Aircraft Information												
Aircraft Manufacturer			Model/	/Seri	ies					Numbe	er	
BEECH			A36						E186	9		
Airworthiness Certificate(s):												
Landing Gear Type: Tricycle												
Amateur Built Acft?	Amateur Built Acft? Number of Seats: 4						3650 LBS Number			er of Engines:		:
Engine Type: Reciprocating			ngine Ma Continen		acturer:		Model/Se IO-550	ries:	s: Rate 285			d Power:
- Aircraft Inspection Information												
Type of Last Inspection		Da	Date of Last Inspection Tim			Time Si	Time Since Last Inspection					tal Time
Unknown							Ho			Hours		
- Emergency Locator Transmitter (ELT) Information											
ELT Installed?/Type		EL	ELT Operated? ELT Aided in Locating Accident Site						ent Site	?		
Owner/Operator Information												
Registered Aircraft Owner			Street A	Addre	ess							
Percival Santos Muniz		-	City							Stat	e	Zip Code
Operator of Aircraft			Street A	ıddre	∋ss							
Percival Santos Muniz	City								e	Zip Code		
Operator Does Business As:				Op	perator Design	nator Co	ode:					
- Type of U.S. Certificate(s) Held:	Vone											
Air Carrier Operating Certificate(s)	:											
Operating Certificate:				\neg	Operator Certific	rate:						
Regulation Flight Conducted Unde	r: Non-U.S. Non-	Commerc		_	Operator Certific	outo.						
Type of Flight Operation Conducted												
Type of Flight Operation Conducted	J. OHKHOWH			_								
	J	FACTUA	L REPO	RT	- AVIATION							Page 2

National Transportation Safety Board FACTUAL REPORT AVIATION

NTSB ID: ERA09WA223

Occurrence Date: 03/08/2009

AVIATION Occurrence Type: Acciden						cident								
First Pilot Information														
Name					City					Sta	te	Date of Birth	Age	
On File														
Sex: M Seat Occupied: Unknown Occupational Pilot? Certificate											e Numl	oer:	•	
Certificate(s):													
Airplane Ra	ating(s):													
Rotorcraft/0	Glider/LTA:													
Instrument	Rating(s):													
Instructor F	Rating(s):													
Current Bie	nnial Flight Revie	ew?												
Medical Ce	rt.: Unknown	Medic	al Cert. Statu	s:					Da	ite of L	ast Me	edical E	xam:	
		•							•					
- Flight Tim	ght Time Matrix All A/C This Make and Model Single Engine Mult-Engine N						ght	Actual	Instrument	Simulated		Rotorcraft	Glider	Lighter Than Air
Total Time														
Pilot In Con	nmand(PIC)													
Instructor														
Instruction	Received													
Last 90 Day						-								
Last 30 Day														
Last 24 Ho	sed? Unknown	Short	l ulder Harness	Llead2 l Ink	nown		Toyica	l ology Pe	rformos	12			econd Pilot? N	
		3110	uidei Hairiess	oseu: Olik	IIIOWII		TOXICO	Jiogy Fe	Homec	1 5		36	acond Filot: 14	0
	n/Itinerary													
	ght Plan Filed: U	nknown					State		A: .					T: 7
Departure Point Aragarcas									SJVO	sirport Identifier			rture Time	Time Zone
Destination State Airport Identifier														
Fazenda Felicid								SWEW						
Type of Cle	earance: Unkno	wn												
Type of Air	space:													
Weather	Information													
Source of V	Wx Information:													
	Unkno	own												
				FACTUAI	_ REPORT	- AVI	ATIO	N						Page 3

National Transportation Safety Board FACTUAL REPORT AVIATION

NTSB ID: ERA09WA223

Occurrence Date: 03/08/2009

FACIUAL REPORT				Occurrence Date. 03/08/2009									
	AVIATION	С	occurrence -	Accider	nt								
Weather	Information												
WOF ID	Observation Time	Time Zone	e WO	F Elevation	Elevation WOF Dista			tance From Accident Site			Direction From Accident Site		
	Ft. MSL							NM					Deg. Mag.
Sky/Lowes	st Cloud Condition:				Ft. AGL			Condition of					
Lowest Ce	iling:		Ft. AGL			Visibility:			SM Altimeter:			"H ₂	
Temperatu	ıre: °C		°C	Weath	er Cond	itions at Acci	dent S	Site:					
Wind Direct	ction:	Wind S	peed:	•		Win	d Gusts:						
Visibility (F	RVR): Ft.	y (RVV)	;	SM									
Precip and	d/or Obscuration:												
Accident	Information												
	Information mage: Destroyed		Ai	ircraft Fire: I	None				Aircraft Exp	olosio	n		
			Ai	ircraft Fire: I	None				Aircraft Exp	olosio	n		
Aircraft Da		Fatal	Ai	ircraft Fire:		None	TOTAL		Aircraft Exp	blosio	n		
Aircraft Da	mage: Destroyed	Fatal 1	<u> </u>			None	TOTAL 1		Aircraft Exp	olosio	n		
Aircraft Da	mage: Destroyed mmary Matrix		<u> </u>			None	-		Aircraft Exp	olosio	n		
Aircraft Da	mage: Destroyed mmary Matrix llot d Pilot		<u> </u>			None	-		Aircraft Exp	olosio	n		
- Injury Su First Pi Second	mage: Destroyed mmary Matrix llot d Pilot		<u> </u>			None	-		Aircraft Exp	blosio	n		
- Injury Su First Pi Second	mage: Destroyed mmary Matrix llot d Pilot at Pilot nstructor		<u> </u>			None	-		Aircraft Exp	blosio	n		
- Injury Su First Pi Second Studen Flight I	mage: Destroyed mmary Matrix llot d Pilot at Pilot nstructor		<u> </u>			None	-		Aircraft Exp	plosio	n		
- Injury Su First Pi Second Studen Flight I Check Flight E	mmary Matrix Ilot Id Pilot Instructor Pilot		<u> </u>			None	-		Aircraft Exp	blosio	n		
- Injury Su First Pi Second Studen Flight I Check Flight E	mage: Destroyed mmary Matrix ilot d Pilot ht Pilot nstructor Pilot Engineer Attendants		<u> </u>			None	-		Aircraft Exp	olosio	n		
- Injury Sur First Pi Second Studen Flight I Check Flight E	mmary Matrix Ilot Id Pilot Instructor Pilot Engineer Attendants Crew		<u> </u>			None	-		Aircraft Exp	olosio	n		
- Injury Su First Pi Second Studen Flight I Check Flight E Cabin /	mage: Destroyed mmary Matrix d Pilot d Pilot nstructor Pilot Engineer Attendants Crew		<u> </u>			None	-		Aircraft Exp	olosio	n		
- Injury Su First Pi Second Studen Flight I Check Flight E Cabin / Other C	mmary Matrix Ilot d Pilot instructor Pilot Engineer Attendants Crew Ingers ABOARD -	1	<u> </u>			None	1		Aircraft Exp	olosio	n		

National Transportation Safety Board

NTSB ID: ERA09WA223

FACTUAL REPORT	Occurrence Date: 03/08/2009									
AVIATION	Occurrence Type: Accident									
Administrative Information										
Investigator-In-Charge (IIC)										
Dennis Diaz										
Additional Persons Participating in This Accident/Incid	ent Investigation:									